

TRACK INSPECTION REPORTING FORM

me W Greenwood

Date _____

08/01/2013

Page 1 of 1

of

(Please Print)

✓ Watchman

Inspected From

Hunt Valley

To

luthervul

W.O Number

1162805

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

No new defects noted in area.

Were Switch in the area of Inspected

Yes

NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes_____NO_____

SPECIAL INSPECTION

Yes

NO

Rain Riding Inspection

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

n 

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: TEAM TWO - SECT 1: HV/LU - CM 902N TO

Classification:

Asset:

Alias:

Location:

Work Location:

Work Group:

Site:

Status:

Priority:

Work Type:

Crew:

Warranty Situation Present?

Maintenance Alert? ☐

Work Details

Component:

Position:

Reason for Repair:

Work Accomplished:

Part Failure:

Parent WO:

Telematics Code:

Telematics Transaction:

GL Account:

Total Planned Cost:

Total Actual Cost:

Repair Limit Amount:

Reported By:

Reported Date:

Asset Details

Primary Meter:

Multiple Assets, Locations and CIs Filter

Tasks Filter 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>	<input type="text"/>	N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARD	<input type="text"/>	<input type="text"/>	N			NONE	COMP

labor Materials Tools Failure Reporting

Labor Filter 1 - 1 of 1

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	<input type="text" value="WGREENWOOD"/>	<input checked="" type="checkbox"/>	<input type="text" value="08/01/13"/>	<input type="text" value="07:00:00"/>	<input type="text" value="11:00:00"/>	<input type="text" value="4:00"/>	<input type="text" value="26.29"/>	<input type="text" value="N"/>	<input type="text" value="N/A"/>

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Page 1 of 1

W.O Number 1162818

[illegible]

Item	COMMENTS
------	----------

No new defects noted in area.

Were Switch in the area of Inspected Yes _____ NO ✓

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes_____NO_____

SPECIAL INSPECTION Yes ☐ NO ☒ Rain Riding Inspection

Reason for special Inspection ? _____

Track Inspector Signature

Supervisory Certification

n AB

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Quick Reporting

Specifications

Work Order	1162818	TEAM ONE - SECT 2: LU/CS - CM 586N TO	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP
Asset			Priority	1
Alias			Work Type	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	
Work Location			Warranty Situation Present?	N
Work Group*	MTA527		Maintenance Alert?	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	105.16
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	07/26/13 12:36:38 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

abor Materials Tools Failure Reporting

Labor Filter 1 - 1 of 1

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	WGREENWOOD		08/01/13	11:00:00	03:00:00	4:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

me Walter W. Bryant

Date 08-02-13

Page 1 of 1

(Please Print)

Watchman

D. Bryant

Inspected From

Cold Spring

To

Camden

W.O Number

1162665

Depot Line

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.	<u>218+10</u>	<u>—</u>	<u>—</u>	<u>1</u>	<u>4w</u>	<u>—</u>	<u>301w</u>	<u>332</u>	<u>Y</u>	<u>N</u>
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

1	<u>Track 1 at Cm 218+10 - North. 10 ties pumping under load. 1/2 - 3/4". Area is mark in yellow. to get to the area, come by 41st. Sears building, thru the access Rd. It's right across from the CHI house.</u>

Were Switch in the area of Inspected

Yes ☒

NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO ☐

SPECIAL INSPECTION

Yes ☐


NO ☒

Reason for special Inspection ?

Walter W. Bryant

Track Inspector Signature

Supervisory Certification



Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1162665	TEAM TWO - SECT 3 - CM 235N/16S AND	Site	LTRAIL
Classification	MTA \LTRAIL	MTA - LTRAIL	Status	COMP
Asset			Priority	1
Alias			Work Type	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	
Work Location			Warranty Situation Present?	N
Work Group	MTA527		Maintenance Alert?	<input type="checkbox"/>

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	07/26/13 12:29:09 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and Cls Filter

Tasks Filter 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARD			N			NONE	COMP

Labor Filter 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	GLAM	<input checked="" type="checkbox"/>	08/02/13	06:00:00	02:00:00	8:00	26.29	N	N/A
	WBRYANT	<input checked="" type="checkbox"/>	08/02/13	06:00:00	02:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Page 1 of 1

W.O Number_

11627.33

[illegible]

COMMENTS

No new defects noted in area

Were Switch in the area of Inspected Yes ☒ NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO

SPECIAL INSPECTION Yes_____ NO_____

Reason for special Inspection ?

Worches Greenwood

Track Inspector Signature

Supervisory Certification

tion M. Bayl

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: **1162733** TEAM ONE - SECT 4: CY/LINT - CM 16S TC Site: **LTRAIL**

Classification: **MTA \ LTRAIL** MTA - LTRAIL Status: **COMP**

Asset: Priority: **1**

Alias: Work Type: **PM**

Location: **CHAIN_MARK** LT Rail Chain Markers Crew:

Work Location: Warranty Situation Present? **N**

Work Group: **MTA527** Maintenance Alert? ☐

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	07/26/13 12:32:41 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDART			N			NONE	COMP

abor Materials Tools Failure Reporting

New Row

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	08/02/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	WGREENWOOD	<input checked="" type="checkbox"/>	08/02/13	07:00:00	03:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

by Walter W. Bryant Date 08-03-13 Page 1 of 1
(Please Print)
Watchman G. LAM
Inspected From Linthicum To Croftwell W.O Number 1162744
BWT

Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair	
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

[illegible]

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes ☒ NO ☐

SPECIAL INSPECTION Yes _____ NO ☒

Reason for special Inspection ?

Walter W. Byrnt

Track Inspector Signature

Supervisory Certification

on 

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action [Icons]

Quick Reporting Specifications

Work Order	1162744	TEAM TWO - SECT 5: LINT/CROM - CM 35	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	CLOSE
Asset			Priority	1
Alias			Work Type	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	
Work Location			Warranty Situation Present?	N
Work Group	MTA527		Maintenance Alert?	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	07/26/13 12:33:16 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Download

Tasks Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	CLOSE
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	CLOSE

labor Materials Tools Failure Reporting

New Row

Labor Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	GLAM		08/03/13	06:00:00	02:00:00 F	8:00	26.29	N	N/A
	WBRYANT		08/03/13	06:00:00	02:00:00 F	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row